

DD 200 Core Rig -How to install the jack screw

What is it for? When customers cannot anchor the rig by mechanical anchor or with a vacuum pump, place a 2x4 on top of jack screw and run board up to the ceiling, against a structural support beam, and tighten down to anchor the rig.



3 components of jack screw




Black fittings (may come connected to each other, unscrew first)



3 Unscrew bolt and remove black cap from top of stand



Thread jack screw into black fitting at top of stand, tighten hex nut



View of top of rig stand, black cover and bolt removed



Drop in larger black fitting with internal threads



Slide in smaller black fitting with the square opening for ½ drive and tighten to keep in place